## Liquid X-SP1000

Anyway, cleaning of the sputtering is simple! For set jig, Construction machine / Thick work of steel frame etc.

**EX:** Customer iig










Trial use X-SP200





Before use X-SP1000

After use X-SP1000 (1 month)
Spray 1 time/day
air blow 1 time/day





EX: Spatter peeling of the steel Conventional product spray coating

- Peelig off with sander, jet chisel
- X-SP1000 spray coating
- Air blow + Wiping
- ※ painting after degreasing agent washing ⇒ Cross cut test is OK



新光機器株式会社 TEL: +81-52-504-5150 SHINKOKIKI Co., Ltd. FAX: +81-52-504-5158